


## IPMAE9-0100A


1200mm pole




## Dimensions (mm/inch)



## **Installation Steps**





Step 1 Insert the damping ring and waterproof ring of cable into the bracket housing.

Step 2 Cover the spherical bracket with bracket housing.

Step 3 Use three M6×20 socket head cap screws to fix the bracket housing to the Camera.

Parameter	
Model	IPMAE9-0100A
Color	White
Working Temperature	-30 °C to +65 °C (-22 °F to 149 °F)
Working Humidity	10%–90% (no condensation)
Material of Housing	Aluminum
Dimensions	$\Phi60.0\times1278.3$ mm ( $\Phi23.6\times503.3$ inch) (OD $\times$ H)
Net Weight	4.7 kg (10.4 lb)
Gross Weight	6.7 kg (14.8 lb)
Mounting	Vertical mount